

## Vehicles with Complicated Battery Replacement

**The vehicle brands and all models under these brands, identified below,  
will now trigger ADDITIONAL SERVICE FEES  
for battery replacement.**

ALFA ROMERO  
ASTON MARTIN  
AUDI  
BENTLEY  
BMW  
FERRARI  
FREIGHTLINER  
HINO  
JAGUAR  
LAMBORGHINI  
LAND ROVER  
MASERATI  
MERCEDES BENZ  
PANOZ  
PETERBILT  
PORSCHE  
ROLLS-ROYCE

Additionally, ALL CLASS A vehicles requiring MULTIPLE BATTERY REPLACEMENT, WILL incur additional fees.

The balance of this list provides Brand specific vehicles that can also require additional service fees.

### BUICK

Enclave	LaCrosse	LeSabre	Lucerne	Terraza
---------	----------	---------	---------	---------

2nd Row Passenger Floor

Trunk

### CADILLAC

ATS	CS	DTS	ELR	Seville
	CT6	DeVille	Escalade	

				Under Rear Passenger Seat
				Trunk
<b>CHEVROLET</b>				
C4500 Kodiak	Cobalt	Monte Carlo	SS	T6500
C5500 Kodiak	Corvette	Silverado 1500	Tahoe	T7500
C6500 Kodiak	Cruze	Silverado 2500	Traverse	T8500
C7500 Kodiak	HHR	Silverado 3500	Trax	
Camaro	Impala	Silverado 4500	Uplander	W4500 Tiltmaster
Caprice	Lumina	Silverado 5500	Venture	W5500 Wiltmaster
	Malibu	Silverado 6500	Volt	W5500 Tiltmaster
				On Frame Rail
				Under Hood with Obstructions
				Trunk
<b>CHRYSLER</b>				
200	Cirrus	Grand Voyager	LHS	Sebring
300	Concorde	Intrepid	Prowler	Voyager
				Wheel Well
				Under Hood with Obstructions
				Trunk
<b>DODGE</b>				
Avenger	Charger	Intrepid	Magnum	Stratus
Challenger	Durango	Journey	Sprinter 2500	Viper
				Wheel Well
				Trunk
<b>FORD</b>				
E-150	F-150	C-Max	GT	Transit-150
E-250	F-250	Escape	LCF	Transit-250
E-350	F-350	Fusion	Thunderbird	Transit- 350
E-450				
				Computer Reset
				Passenger Frame Rail
				Under Driver's Seat
				Trunk
<b>GENESIS</b>				
	G80		G90	
				Trunk
<b>GMC</b>				
Acadia		C4500 Topkick		T6500
Sierra		C5500 Topkick		T7500
Yukon		C6500 Topkick		W4500 Forward
		C7500 Topkick		W5500 Forward
				On Frame Rail

				Under Hood with Obstructions
<b>HYUNDAI</b>				
Equus	Genesis		Sonata	Tucson
				Trunk
<b>INFINITI</b>				
M35H	Q50		Q60	Q70
				Trunk
<b>JEEP</b>				
Grand Cherokee				
Wrangler (Auxillary Battery)				
				Under Front Passenger Seat
<b>KIA</b>				
Forte5		Niro		Optima
				Under Hood with Obstructions
				Trunk
<b>LEXUS</b>				
CT200h	HS250h	LS500	LFA	RX350
ES300h	LC500	LS500h	LS600h	RX40h & hl
GS450h	LC500h		NX300h	UX250h
				Computer Reset
				Trunk / Cargo Area
<b>LINCOLN</b>				
LS		MKX		MKZ
				Under Hood with Obstructions
				Trunk / Cargo Area
<b>MAYBACH</b>				
	57		64	
				Trunk / Cargo Area
<b>MAZDA</b>				
Miata				
				Trunk / Cargo Area
<b>MINI</b>				
Cooper				
				Computer Reset
				For some - Wheel Well
<b>MITSUBISHI</b>				

ALL BOX TRUCKS		Lancer		Outlander
				On Frame Rail
				Trunk / Cargo Area
NISSAN				
Rogue				
				Trunk / Cargo Area
OLDSMOBILE				
	Aurora		Silhouette	
				Under Hood with Obstructions
				Rear Seat
PLYMOUTH				
Breeze				
				Wheel Well
PONTIAC				
Aztek	G5	GTO	Grand Prix	Trans Sport
Bonneville	G8	Grand Am	Montana	
				Under Hood with Obstructions
				On Frame Rail
				Rear Seat
				Trunk / Cargo Area
RAM				
ProMaster1500		ProMaster2500		ProMaster3500
				In Driver's Foot Well
SATURN				
Ion		Outlook		Relay
				Back Passenger Foot Well
				Trunk / Cargo Area
SMART				
Fortwo				
				Front Passenger Foot Well
TOYOTA				
Avalon	Highlander	MR3 Spyder	Mirai	Prius
Camry				RAV4
				2nd Row Passenger Seat
				Trunk / Cargo Area
VOLKSWAGEN				
Atlas	EOS	GTI	Jetta	Tiguan
Beetle	EuroVan	Golf	Passat	Touareg
CC			Phaeton	E-Golf

				Computer Reset
				Under Driver's Seat
				Under Hood with Obstructions
<b>VOLVO</b>				
C70	S80	S90	V70	XC70
S60				XC90
				Trunk / Cargo Area